

Service Bulletin

Nr. / no. **045-2020**

Erstellt am / made on: **06-02-2020**

Geräte/devices

<input type="checkbox"/> KD1x1	<input type="checkbox"/> KD2x2	<input type="checkbox"/> KD3x3	<input type="checkbox"/> KD3x3-F	<input type="checkbox"/> KD4x4	<input type="checkbox"/> KD4x4-F	<input type="checkbox"/> KDB/KDD
<input type="checkbox"/> HD Etronic I	<input type="checkbox"/> HD Etronic II	<input type="checkbox"/> HDE	<input type="checkbox"/> HDE-F	<input type="checkbox"/> HDB/HDD	<input type="checkbox"/> KW	
<input type="checkbox"/> KS	<input type="checkbox"/> KSM	<input type="checkbox"/> HSC	<input type="checkbox"/> MP			
<input type="checkbox"/> SmartWash	<input type="checkbox"/> SW Plus	<input checked="" type="checkbox"/> JetWash	<input checked="" type="checkbox"/> JW Plus	<input checked="" type="checkbox"/> CW Plus		
<input type="checkbox"/> CompactLine	<input type="checkbox"/> ModulLine	<input type="checkbox"/> Vacs				

Qualitäts-Optimierung durch neue HD-Pumpen im CarWash-Bereich

Ab sofort wird der Einbau und Vertrieb für die bisherige HD-Pumpe C3W2015 SSL Ø20 (Art.-Nr. 361315), mit gelben Gewebe-Dichtungen eingestellt.

Nachfolger ist die HD-Pumpe E3B2015 SSL Ø20 (Art.-Nr. 361424), mit Teflon-Dichtungen.

Die Rep.-Sätze 361332, 361333, 361334 und 361340 bleiben identisch.

Der Rep.-Satz 361338 wird durch 361455 neu ersetzt.

Der Rep.-Satz 361337 wird durch 361456 neu ersetzt.

Quality optimization through new HP pumps in the CarWash area.

From now on the installation and sales for the previous HD pump C3W2015 SSL Ø20 (item no. 361315) with yellow tissue seal will be stopped

The successor is the HD pump E3B2015 SSL Ø20 (item no. 361424), with Teflon seals.

Repair kits 361332, 361333, 361334 and 361340 will be the same.

Repair kit 361338 will be replaced by 361455. Repair kit 361337 will be replaced by 361456.



Anlage / attachment

geprüft am / checked on:

14-02-2020

genehmigt von / approved by:

Helmut Glas